

	· · · · · · · · · · · · · · · · · · ·)
	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	١
	Aircraft warming up.	OR COMMANDING OFFICER'S REPORT: R170	,
	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: TN /7 5 T/V	
	Aircraft turned over onto its nose	COMPOSITION:	`
	during warming up.		,
,)
İ)	RECOMMENDATIONS:	,
	igvee		٠,
	PRIMARY CAUSE:	Nil)
	Chocks slipping on ice letting)
	aircraft slide forward - the locked wheels then hit dry pave-	·	
)	ment and the sudden stop caused	ACTION TAKEN:)
	aircraft to nose over.	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
wett.	3/6.	See that snow and ice is removed thus preventing)
(1)	de Noing up on hove.	the chocks from slipping when motors are run up by pilots.)
1)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		/ }
	Aircraft nesed over		, ,
[]:		RECORDED BY DATE	,
)		CHECKED BY DATE)
))