



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

**Taxiing along field.**

OR COMMANDING OFFICER'S REPORT:

1170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

*TCO / ACT*

**Port lower wing struck boundary light  
when taxiing along leaward side of  
field causing damage to port wing,  
(lower port wing).**

RECOMMENDATIONS:

**Nil**

PRIMARY CAUSE:

~~Pilot failed to see boundary light  
in time to avoid accident.~~

*11. Other*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Nil**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Port lower wing struck boundary  
light.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_