

}	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFIC	ER	
)	Flying training. NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 1LOC/1/4 C	R170 1555/00/01)
)	Aircraft went into a spin from a gliding turn at approximately 500 feet. Pupil failed to complete his recovery before the aircraft hit th ground.	COMPOSITION:)
)	PRIMARY CAUSE:	Nil)
) Pupil held off bank in a gliding) turn, causing aircraft to spin.				
·)))	19. Out of Contral	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTH N11	!ER)))
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:				
	Aircraft spun into the ground, due to insufficient altitude to recover	•	RECORDED BY	DATE)
)			CHECKED BY	DATE)
))))))))))