

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Formation flight.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: R170
Coming in to land from formation flight when both engines cut in succession. Forced landing made	DATE: COMPOSITION:  LIPPING  R170
with undercarriage retracted.	RECOMMENDATIONS:
	Nil
PRIMARY CAUSE:	
Engines failed in succession and forced landing made with undercar retracted.	riage <u>ACTION_TAKEN:</u> (A) Disciplinary (B) Technical (C) Other
Engines failed in succession and forced landing made with undercar retracted.	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other  Admonished. Log book endorsed -  "Faulty Cocknit Daill - Conclusion "
Engines failed in succession and forced landing made with undercar.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Admonished. Log book endorsed -  "Faulty Cockpit Drill - Carelessness."
Engines failed in succession and forced landing made with undercar retracted.  17. Vorced Lande  SECONDARY CAUSE OR CONTRIBUTING FACTORS:	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Admonished. Log book endorsed -  "Faulty Cockpit Drill - Carelessness."  RECORDED BY DATE