

| On bombing detail. | COURT OF INQUIRY, INVESTIGATING OFF OR COMMANDING OFFICER'S REPORT: | R170 | |
|--|--|-------------|------|
| NATURE OF ACCIDENT AND STAGE OF FLIGHT: Shortly after take-off, engine cut out on changing from fine to | DATE: COMPOSITION: | Frymer, | 15 |
| coarse pitch causing forced landing with damage to U/C and main planes through A/C striking tree. | ng RECOMMENDATIONS: | | |
| PRIMARY CAUSE: | Nil | | |
| Engine cut out on changing pitch. 13. Forced Land | ACTION TAKEN: (A) Disciplinary (B) Technical (C) O Nil | THER - | |
| SECONDARY CAUSE OR CONTRIBUTING FACTORS: Corced landed and at report struck 26. English Trouble Accus | trees. | RECORDED BY | DATE |
| an sugare production success | cent | CHECKED BY | DATE |