

)))))))))))))))))))	
DUTY ON WHICH ENGAGED: Instructor demonstrating spins. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Instructor unable to recover from a spin after trying normal methods ordered his student to abondon a/c at 2000'. Student had trouble withhis harness and at 1000'assisted by Institute The aircraft hit the ground in a left PRIMARY CAUSE: spin and turned over on back. Both airmen parachuted safely the ground.	is PRECOMMENDATIONS: tor. ft
Primary Cause: Inability to recover A/C from a demonstrated spin remains indeterminate. L. Dut af Cause of Contributing Factors:	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER CONCLUSIONS OF A.I.B. Possible that accident due to improper method of spin recovery as instructor had only instructed for three days. Instructor to be commended in extricating pupil before jumping himself. This action took place at low altitude.
	CHECKED BY DATE)