

)	· · · · · · · · · · · · · · · · · · ·)))))))))))))
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER WILLT
)	Solo practice.	OR COMMANDING OFFICER'S REPORT: Investigating Officer's
		investigating Officer's
,	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 8-2-42 / C 7 / Report"
)	Airscrew of No 4318 contacted	COMPOSITION: / CA// CA/
)	emponnage of No. 4962, cutting off	F.O. McGill, E.R. No. 19 E.F.T.S. Virden, Man-
,	rudder and part of elevator, Pilote	And In Bell 1000 vill doll, mail.
,	jumped with parachutes. Both	
)	aircraft spun in the air and nosed	RECOMMENDATIONS:
)	down into a dive.	Stress both in the air and on the ground the importance
, 1	PRIMARY CAUSE:	of keeping a sharp lookout at all times. Also the
,	_ · · · · · ·	consequences of negligence such as endorsement of
)	Negligence. Neither pilot exercised caution in keeping a proper lookout.	pilot's Log Books.
)	21. bellisions ale	·
1	d. Dellusions surc	ACTION TAKEN:
,		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
)	$\langle \cdot j \rangle = \hat{j}$	Whole school cautioned again of importance of looking
)	Ŷ	around more. Both pilots awarded detention:-
,		Terriff - 72 hours. Sheen - 96 hours. Both pilots
	CTCCV7.	Log Books endorsed. Conclusions of A.I.B.
)	- THE PROPERTY OF CONTRIBUTING PACTORS:	
) (Aircraft abandoned and crashed.	Pilots' failure to keep lookout for other a/C.
)		RECORDED BY DATE
,		\dot{j}
)		CHECKED BY DATE
)		