

DUTY ON WHICH ENGAGED:

Taxiing.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

01467
R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot while taxiing failed to see other aircraft standing and collided with aircraft No. 4953.

DATE:

TCA / 107
MAY 1953

COMPOSITION:

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Failure to see parked aircraft.~~

9. Collision

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

All pupil pilots cautioned to the importance of taxiing slowly and keeping a sharp lookout on both sides and around for aircraft on the ground and in the air.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Collided with aircraft No. 4953.~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____