

DUTY ON WHICH ENGAGED: Routine o bservers exercise.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	)
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Complete engine failure caused forced landing in farmers field.	R170  DATE: COMPOSITION:	<b>)</b>
	RECOMMENDATIONS:	)
PRIMARY CAUSE: Connecting rod failure engineering officers report following.	Nîl	)
17. Forced Landing	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil	)
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Engine failure caused by No. 4 connecting rod going through the port block. Forced landing.  More FORM LY RED. 1247 10M-15-11-41	RECORDED BY DATE	)
(LAFF FORM LEGI REG. 1247 10M—15-11-41	CHECKED BY DATE	<i>)</i>