

DUTY ON WHICH ENGAGED: Solo practice.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	R.170  DATE:
5105 returned to tarmac because	DATE: COMPOSITION: TOP/XA  TOP/XA
of faulty brakes-stopped at edge	TCHYXA
of tarmac and was taxifed into by 4972 which was taxifing slowly	
along tarmac with men on wing tip.	RECOMMENDATIONS:
PRIMARY CAUSE:	
Failure on part of the pilot and	
mechanic to maintain proper lookout	t
9. Callisian	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
(1)	(A) Pupil and ground crew man of 4972 severely
	reprimanded.
/ · · · · · · /	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Aircraft collided on ground.	
	RECORDED BY DATE