

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER Gunnery exercises. OR COMMANDING OFFICER'S REPORT: Investigating Officer's Report. NATURE OF ACCIDENT AND STAGE OF FLIGHT: 13-4-42 /M/16 /2/-/1/1/AE/SA DATE: While waiting to start gunnery COMPOSITION: exercise at 3000 ft. A/C caught F.L. Prendergast, H.L. (C1644) No.2 B&G School. fire and pilot force landed. Mossbank. Sask. A/C burned up on ground. RECOMMENDATIONS: Instructions were issued to all flying personnel that immediately a glycol leak occurs, the pilot should turn off his petrol and apply to and use A/C caught fire in the air which the K.C.A.F. proceedure against fire while was caused by glycol leak caused air-borne." by a failure of the connecting rods in No. 2 big end. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Conclusions of A.I.B. Following instructions issued: This accident was due to fire in Action to be taken in the event of a glycol leak the air following on a major glycol in the air: leak caused by a failure of the (i) A glycol leak is recognized by white smoke coming connecting rods in No.2 big end. out of the exhaust. SECONDARY CAUSE OR CONTRIBUTING FACTORS: (ii) A violent explosion will denote that a connecting Forced landing and fire which rod has been thrown out of the Side. If this happens destroyed the aircraft. the pilot should switch off his petrol, open up his Dr. Feir - tu tui engine fully and switch off. If these instructions are followed, no fire will result.