

))))))))))))))))))) 	COURT OF MOUNDY INVESTIGATING OFFICER
Solo practice.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Student failed to keep A/C straight after landing, ground looped.	DATE: COMPOSITION: LS/P55
grander in the	
	RECOMMENDATIONS:
PRIMARY CAUSE:	
Inexperience. of the pilot in that	
e overcorrected when the a/c starte	ed.
to turn.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
(2) Jung	Pilot was rechecked on runways and sequence #20.
•	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Fround loop.	RECORDED BY DATE
	CHECKED BY DATE
	CHECKED BY