

DUTY ON WHICH ENGAGED: Sequence 6 7 9 16.	COURT OF INQUIRY, INVESTIGATING OFFICER COMMANDING OFFICER'S REPORT:))))) CER)))))	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: LS/22 S	•			
Ground loop during landing.					
Trainee apulied rudder upon landing causing ground loop to the left.					
and					
	RECOMMENDATIONS:				
PRIMARY CAUSE:					
Ground loop during landing.					
(2) Luung	ACTION TAKEN:				
	(A) DISCIPLINARY (B) TECHNICAL (C) OTH Check by flight Commander.	ER			
	Log book entry.				
SECONDARY CAUSE OR CONTRIBUTING FACTORS:					
Inexperience.					
		RECORDED BY		DATE	
		CHECKED BY		DATE	