

Solo night flying.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	R170))
NATURE OF ACCIDENT AND STACE OF FLIGHT: Pupil thought he was overshooting on first approach and so throttled	DATE: COMPOSITION: LUJO)
back. While correcting for slight drigt he noticed the altimeter was showing just below 100 ft. above ground level and immediately started	RECOMMENDATIONS:)
to open up, hit fence and pancaked primary CAUSE: into the ground.	Nil)
Pilot undershot when approaching to land at night and lost airspeed.)
) ? Undershal	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
	Pilot warned. Log book endorsed "Error of judgment.")
secondary cause or contributing factors: A/C flying low hit the boundary			,
fence and pancaked into the ground.	RECORD	DED BY DATE	,
)	CHECKE	ED BY DATE)
)