

DUTY ON WHICH ENGAGED: Wind speed and direction practice.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:			
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pupil pilot landed against red	DATE: COMPOSITION:	R170	e. E	
lights from Control Trailer, did not take over shoot action, an failed to pull up, and ran into rough ground beyond the runway when the undercarriage was torn	<b>d</b> RECOMMENDATIONS:			
PRIMARY CAUSE:		Nil		
Negligence on the part of the pilot in that he disobeyed Station Standing Orders and he did not take over-short action when it was apparent that there was a risk in continuing the landing.    Autuskal	ACTION TAKEN:  (A) DISCIPLINARY (B)		<sup>HER</sup> en against pup:	il pilot.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:  Over-shot and ran into rough ground Undercarriage was torn off arter over-shooting runway.	d•		RECORDED BY	DATE
			CHECKED BY	DATE
				DAIL