

circuits and landings. NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: B170	
The stadent pilot was on his second solo flight and was attempting to	COMPOSITION: LH//5/4.4	
make a wheel landing. The student brought the control column back		
sharply, the A/C stalled, dropped a wing and nosed over onto its back.	RECOMMENDATIONS:	
PRIMARY CAUSE:	Nil	
Pilot brought control column back too sharply. 7. Other	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
	Pilot requested to cease training.	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
Aircraft stalled and nosed over onto its back.	RECORDED BY D	ATE