

í)))))))))))))))))))))))))))))))
)	DUTY ON WHICH ENGAGED: Scheduled gunnery exercise.	COURT OF INQUIRY, INVESTIGATING OFFI OR COMMANDING OFFICER'S REPORT:	<u>CER</u>)
)	On completion of exercise a/c structure ground and bounced into the air. Pilot opened the throttle slightly	•	R.170)
)	but found he had set the throttle nut too tightly. Again a/c struck the ground and bounced. Pilot made another circuit and successful PRIMARY CAUSE landing. Error in judgment on part of pilot.	RECOMMENDATIONS:)))
) , , , , , , , , , , , , , , , , , , ,	HE AVY	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C)	Стнея)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft was slightly damaged after bouncing several times on landing.		RECORDED BY	DATE)
) 1	R.C.A.F. FCRM L20 RE2. 1247 10M-+5.11.41		CHECKED BY	DATE)