

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OF	FICER R. 170)
Routine training flight.	OR COMMANDING OFFICER'S REPORT:		
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: May 19th and 20 th,	1942.	
Engine failed on taking off.	COMPOSITION:		,
Aircraft struck ditch and over-	F/O D. Boyle No. 9 H	L.F.T.S., R.C.A.F. St. Catheri	, De
turned in vineyard. Upper main pla)
both lower planes, two undercarriag)
"V" struts, rudder and propellor	RECOMMENDATIONS:		
were damaged.	All trainees have again	been warned of the importance	,
	of both looking at and f	eeling that switches and)
PRIMARY CAUSE:	gas cocks are properly t	urned on.)
Mishandling of augiliary controls			,
in taking off with gas cocks closed	-	;)
FORCED LAND	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other)
	Dunil milet mineriches	Tan bash sudamad)
	Pupil pilot admonished. "Gross Carelessness."	Log book endorsed	,
Market State Control	"Gross Caretessness."	:)
))
SECONDARY CAUSE OR CONTRIBUTING FACTORS:			à
ENCINE TROUBLE - ACCIDENT			,
Aircraft struck ditch and overturned		RECORDED BY DATE	1
in vineyard, damaging upper main pla			
both lower planes, two undercarriage	B TEA A CONTRACTOR OF THE PERSON OF THE PERS	CHECKED BY DATE	ì
struts, rudder and propellor.		DATE ,	,
)