

DUTY ON WHICH ENGAGED:	COURT OF INCLUDY DIVERTION OF SECTION
	COURT OF INQUIRY, INVESTIGATING OFFICER
Instrument flying.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Investigating Officer's Report
After 40 mins. instrument flying Instructor took over and indulged	COMPOSITION: /LCo/ACC/POL
in low flying striking a tree about	, ,
25' from the ground. A/C crashed	
inverted in swampy ground.	RECOMMENDATIONS:
Disobedience of Station Standing Orders re low flying. COLLISIONS OBSTRUCTIONS	In future monthly practice instrument flying be given by instructors specifically detailed by C.F.I. When two trained pilots are on mutual training flight the senior pilot be made responsible for obeying of regulations laid down. Not concurred in by A.O.C Second recommendation contrary to CAP 100 Sec.6, para 4. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Instructions being issued to all units that such flights as this be authorized by Flight Commanders. ONCLUSIONS OF A.I.B. Agree with findings and remarks of A.O.C. re Recommendations.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	metadions,
Aircraft hit tree and crashed to	
the ground, while attempting a stee climbing turn close to ground, stal and struck tree. DISO BEDIENCE O	led (),
R.G./A.F. FLAM LOS RES. 1247 1031—15-11-41 ORDERS.	CHECKED BY DATE)