

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER R170	
Low Tlying.	OR COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: ILOC / A COMPANDINO OF THE RESIDENCE AND A COMPANDINO OF THE RESIDEN	
Stalled low over slough and fell in.	COMPOSITION:	
	RECOMMENDATIONS:	
	Nil	
PRIMARY CAUSE:		
Gross carelessness on part of		
instructor in allowing aircraft to stall and settle in lake.		
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
BUT OF CONTROL	Pilot was assessed the sum of \$63.90 towards the cost of removing the aircraft from the lake and making the necessary repairs. His log book was endorsed "Gross Carelessness".	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	Instructor admonished.	
Aircraft landed in lake.	RECORDED BY DATE	-
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE	_