

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER Instructional flight. OR COMMANDING OFFICER'S REPORT: Court of Inquiry NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 14-5-42 A/C took off with Sgt. Chapman in COMPOSITION: front seat giving instructions to Pres. S.L. A.C. Bailey (2810b) #31 E.F.T.S. De Wintyn LAC. Thompson. Shortly after a/c Mem . F.L. R.A. Gilmour (C1578) #55 F.T.S., Claresnolm made a gentle turn to the right F.O. J.B. Dinning (J3713) #5 E.F.T.S.High Rive. then went into a spin to the right RECOMMENDATIONSJ.S. Mason (37127) #31 E.F.T.S.De Wint(). and continued to spin until it hit Nil the ground totally damaged. Propellor PRIMARY CAUSTIAS not turning when a/c crashed. Feilure of either occupant of the aircraft to take recovery action. OUT OF CONTROL ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Conclusions of A.I.B. The a/c on an authorized training flight struck the ground while recovering from a spin. The evidence points to the fact that the instructor SECONDARY CAUSE OR CONTRIBUTING FACTORS: was piloting the a/c and that he failed to recover The e/e struck the ground in a from the spin, possibly dug to physical disability. to the right. R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41 CHECKED BY