

DUTY ON WHICH ENGAGED: Instructional training.	COURT OF INQUIRY, INVESTIGATING OFFI OR COMMANDING OFFICER'S REPORT:	CER	<u>R170</u>
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Failed to clear fence, cracking main spares on both lower main	DATE: LF17 / COMPOSITION:	a promprogram	
planes.			
Engine failed to respond when demonstrating forced landing approach	RECOMMENDATIONS:)
PRIMARY CAUSE:	Nil		· .
Failure of engine to respond to throttle properly.			,
COLLISIONS ORSTRUCTIONS	ACTION TAKEN: (A) Disciplinary (B) Technical (C)	CTHER)
	N11)
SECONDARY CAUSE OR CONTRIBUTING FACTORS:			1
Aircraft hit fence.		RECORDED BY	DATE)
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41		CHECKED BY	DATE)
))))))))))	1 1 1 1	