

DUTY ON WHICH ENGAGED:

Practice single engine landing.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**Pilot ran into tarmac excavation
on edge of landing area.**

DATE:

R170

COMPOSITION:

L0/000

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Error of judgment in landing,
and carelessness on the part of the
pilot in attempting to land with
insufficient room and failing to
take overshoot action.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action is being taken against
LAC. Aldersley. Pupil's Log Book endorsed.

? OTHERS.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/G ran into tarmac excavation.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____