

į	· · · · · · · · · · · · · · · · · · ·)
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
)	Night time dual instruction.	OR COMMANDING OFFICER'S PERCET: COURT OF INQUIRY	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:)
``	A Time county middenly atmine the	COMPOSITION: ILCG/WM)
)	A line squall suddenly struck the airport causing a wind shift and	F/L Sharpe E.W.C. (C2797) No. 2 T.C. Winnipeg, Man.)
)	conditions of poor visibility. Tiges	r	
,	Moth 3878 encountered this condition	RECOMMENDATIONS:)
)	so pilot endeavoured to let down through it. It was then a/c struck	More emphasis on emergency bad weather flying procedure. Greater stress on value of instructor's inst-	
)	the ground and was destroyed. PRIMARY CAUSE:	rument flying practice. More complete night flying	,
)	PRIMARY CAUSE: Sudden deterioration in weather	equipment for Elementary trainers: (a) Sensitive)
1	conditions during night flying	altimeters (b) Landing lights and/or flares.	
,	operations together with inexperience		`
)	of pilot.		`
	1/	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other Nil.)
,	19. Out of legentral	CONCLUSIONS OF A.I.B.)
, `		Agree with the findings and remarks of the A.O.C.)
,		While agreeing with the findings it is considered that	1
.)	\smile	A/C at E.F.T.S. used in night flying should be equipped	ľ
)	secondary cause or contributing factors: A/C crashed to the ground, caught	with landing lights.	1
)	fire and was totally destroyed.	RECORDED BY DATE	,
)	29. Fire In brash)
1	$\alpha \gamma$.	CHECKED BY DATE	,i
)
レフ			_