



DUTY ON WHICH ENGAGED:

Solo practice. - 3904  
Flying instruction - 5106

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot taxied into aircraft 3904.  
which was parked on way to take  
off position.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

DATE:

COMPOSITION:

TCA/PT  
TCA/PT

R170

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Taxing fast and not looking  
around. Negligence on part of pilot  
of A/C 5106.~~

*9. collisions*

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

7 days detention  
Pilot's Log Book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C 5106 taxied into rear of 3904~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_