

) DUTY ON WHICH ENGAGED: ) Local flying first solo on type.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Port U/C collapsed on landing resulting in ground loop.	DATE: COMPOSITION: 2 UC/F-L/UCL
)	RECOMMENDATIONS:
PRIMARY CAUSE: Incomplete selection of U/C to down position resulted in port U/C being unlocked on landing.  2. June 9	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  (A)
SECONDARY CAUSE OR CONTRIBUTING FACTORS:  Port U/C collapsed, causing A/C  to ground loop.  3.4. U/C Defect  R.C.A.F. FORM L20 REQ. 1247/10M—15-11-41	RECORDED BY DATE