



DUTY ON WHICH ENGAGED:

Target towing exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft 2381 weather cocked while passing and taxied into aircraft 2380 causing damage to port wing of aircraft 2380.

DATE:

R.170

COMPOSITION:

*TCA/TCR/TCR/TCR*  
*TCA/TCR*

RECOMMENDATIONS:

PRIMARY CAUSE:

Poor taxiing procedure.

*9. collisions*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Pilot could not control weather cocking action of A/C. 2381 taxied into 2380.~~

RECORDED BY

DATE

CHECKED BY

DATE