

)			
)	Dual practice in forced landing approaches. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine failed to pick up. Pilot	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: R.170 DATE: COMPOSITION: R.FM / FOR / F	
)))	in attempting to avoid wheat field touched port mainplane in making turn and aircraft crashed.	RECOMMENDATIONS:	
)))	FRIMARY CAUSE: Failure of engine to pick up after forced landing approach when pilot opened throttle too quickly.	ACTION TAKEN:	
; ; ;	17. Forced Canding	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
)	Wing caught in wheat and aircraft crashed. 26 Eugent Cauble - Cecedan	RECORDED BY DATE	
v.	R.C.A.F. FORM L(4) REQ. 1247 10M(5-11-41	CHECKED BY DATE)	