

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Night flying training.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

R170

Pilot of X6544 taxied into rear of stationary X6538.

COMPOSITION:

MCB
TCA/PCT/NAV
TCA/PCT/NAV

Pilot of X6538 failed to keep his identification lights on.

RECOMMENDATIONS:

nil

PRIMARY CAUSE:

~~Pilot mistook rear light for taxiing strip light.~~

9. collisions

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Both pupil pilots cautioned to be more careful in future. *(admonished).*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~One aircraft taxied into the other.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____