

	)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
	)	Sequences 7-9-10-12-15-22.	OR COMMANDING OFFICER'S REPORT:	
	)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: IEDE //OC//F/A/A D-14	
	)	Engine stopped while doing aero-	COMPOSITION:	
	)	batics. Student pilot attempted		
	)	forced landing and spun in from		
	١.	gliding turn.	RECOMMENDATIONS:	
	)		That instructors continually impress students with	
	)		the proper procedure in forced landings and spin	
	)	PRIMARY CAUSE:	recoveries and that more time be devoted to these	
		Inexperience on part of pilot	two sequences.	
	)	in that he got excited and allowed		
ı	)	A/C to go into spin.	)	
	)	Suit of Interior	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  )	
	)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NiL.	
	)		)	
	)		)	
•	)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	,	
1		Engine failed, A/C force landed,	•	
	)	went into spin and failed to recove	Pr. RECORDED BY DATE	
,	)		)	
	)		CHECKED BY DATE	
	)			