

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Chapman-sequences 10-spins & 15 Steep	
Burns,-sequences 10-spins & 15 steep NATURE OF ACCIDENT AND STAGE OF FLIGHT: Lurns	· INVESTIGATING OFFICER'S REPORT.
During unauthorized formation flight	
) aircraft collided in mid air. A/C 5081 was abondoned by LAC Chapman	Squadron Leader W.B. Millar C 592(GL) No. 4 S.F.T.S.) Saskatoon.
and later burned. Aircraft 4963	
) crashed with occupant.	RECOMMENDATIONS:
\	(a) More intensive lectures on dangerous and fool-
) ODUMADY CANCE	hardy flying.
) PRIMARY CAUSE:	(b) Actual visits to the scene of crashes, for all
Inexperience of pupil-pilots in	student pilots.
attempting formation flying.	
Callini Mill	ACTION TAKEN:
roccesions, pro-	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	(a) LAC Chapman was grounded, and is to serve six
	months at an SFTS on aerodrome control duty.
)	Conclusions of A.I.B. Concur in the findings.
)	The accident was undoubtedly caused by the inex-
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	perience of these pupil pilots in attempting form-
Breach of station standing Orders	ation flying. They each had approximately 13 hours
he beth pilots.	solo. RECORDED BY DATE
111-11-1121	G/ ·
) R.C.A.F. FORM L20 REQ. 047 10M—15-141	CHECKED BY DATE