رد ر			A STREET OF SEL	FAIL				STR. CHIMA	onio uni printi		
ď	CAUSES OF ACCIDENTS										
PE OI	High Diror Alto 4		PLACE M.	.A.		H.Q. FILE	1-42 TIM 1100-5]	1430 1-75	1 1 / 6.7		
Ĺ	Tiger Moth		No. 5175		CRASH CAT. B	SE X	de Day	NIGHT	O CAME		
	NAME	RAN	K No.	PUTY	וחותו	RIES	S	ERIOUS	Dakinat		
YPE OF ENGINE		LA	C R127329	P	Nil		SE	CARD ERIAL NO.	S S S S S S S S S S S S S S S S S S S		
F	TYPE A/F NO. EXTENT			DATE	ног		BY PILOTS	5	1 1/37/		
	T.Moth 5175 Serious		ONE NO.		INST. NIGHT	ON TYPE	O DUAL S	LASI			
CATEGO	G.Mjr. 7707/85606 Nij		E COM.	No. & DA	ATE REPOR	PT	FILE	DATE	A G E O F		

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Day routine flying.	OR COMMANDING OFFICER'S REPORT: D.14.
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: COMPOSITION: DATE: COMPOSITION:
Aircraft made heavy landing. Came in nose high, hit with tail wheel first and aircraft came down heavily.	COMPOSITION:
	RECOMMENDATIONS:
	Nil
PRIMARY CAUSE:	
Inexperience.	
4. HEAVY	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other Nil
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
A/G hit with tail wheel first	
and landed heavily.	RECORDED BY DATE
	CHECKED BY DATE
	CHECKED 51 DATE