

(((((((((((((((((((COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: D.14. DATE: TM PC7/I WWG.
(PRIMARY CAUSE: Instructor turned cross wind allowing wind to get under windward wing. (7. 6THERS.	The instructor involved has been instructed that in the future at any time the wind is such as would endanger the aircraft by taxiing it in a strong wind, he is to keep the aircraft headed into the wind until assistance has arrived. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Nil.
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Turned cross wind. Wind eaught under study wing and turned a/c over. R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41	RECORDED BY DATE (