31 30 29 2 Utech Osobice no	//////	////	20 19 18 20 19 18 20 19 18	17 16 15 08 HJ		////	9 8 7	6 5 4 3
U PILOT	OTHERS			FAILU		ENG		URE VI
UNIT Air Mountair	Arm. Scl. COM	li li	E		Ontario.	DATE 25/1 H.O. FILE	1/12 TIME 2	NIGHT ST HET
A/C TYPE	Yale	No.	3398	CR CA	ASH	SE X ME	DAYY	
	Battle NAME	RANK	1998 No.	DUTY	ULNI	RIFS	SERI	OUS > TOR
	sburg, R.B.	<u></u>	2706	Р	Uninjured		FATAL	OUS OF PARTY
YPE OF ENGINE								RD NO. C SHOW REPORTED TO SHOW REPORTED
TYPE A/F & ENGINE	No.	No. EXTENT REPORT SERIAL DATE			но	HOURS FLOWN BY PILOTS		
Yale	3398	DAMAGE FORM	10.		INST. NIGHT	ON TYPE	TOTAL DUAL SOLO	6 MOS. 1 7 1
Rattle	1998						264	A O M AU
SIGNAL N	O. & DATE UNIT	No. & DATE	COM, N	lo & DAT	E REPO	RT F	ILE C	DATE
		NAT	URE	OF A	CCIDENT			
2 (E ) b	5 9 4 8 6	01 11 21	EI PI SI	91 41	81 61 05		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	77 82 62 OE

DUTY ON WHICH ENGAGED:	OURT OF INQUIRY, INVESTIGATING OFFICER	
Night flying practise.	R COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	ATE: TOA/POT	-
Yale 3398 taxied off the north- east end of the taxi strip. Front down in mud. Battle aircraft No.	ATE: DMPOSITION:  TO A / POST  TO B / POST	
1998 of B&G School taxied into tail of Yale 3398 damaging the rudder.	ECOMMENDATIONS:	
	MIL .	
PRIMARY CAUSE:		
Yale negligently taxied off runway		
into mud. (Yale No. 3398)		
	CTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  PILOT ADMONISHED.	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
3&G Battle aircraft 1998 taxied into		
rudder assembly of Yale 3398 with wi	RECORDED BY	DATE
•	CHECKED BY	DATE