

Aircraft was being taxied too close to edge of serviceable part of aerodrome. Turned to avoid another a/c and ran into deep snow. A/C went up on nose. PRIMARY CAUSE: Carelessness, failed to note proximity of edge of aerodrome not compacted. Action Taken: (A) Disciplinary (B) Technical (C) Other Log book endorsed. Secondary Cause or Contributing Factors: Taxied into soft snow, A/C went up on nose. Date: Composition: Action Taken: (A) Disciplinary (B) Technical (C) Other Log book endorsed. Action Taken: (A) Disciplinary (B) Technical (C) Other Log book endorsed.	DUTY ON WHICH ENGAGED: Taxiing.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER Log book endorsed. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Taxied into soft snow, A/C went- up on nose. RECORDED BY DATE	Aircraft was being taxied too close to edge of serviceable part of aerodrome. Turned to avoid another a/c and ran into deep snow. A/C went up on nose. PRIMARY CAUSE: Carelessness, failed to note preximity of edge of aerodrome	RECOMMENDATIONS: Recommend slower taxiing under winter conditions with
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Taxied into soft snow, A/C went up on nose. RECORDED BY DATE) /1. OTHERS	
up on nose. Recorded by DATE)		Log book endorsed.)
B 0.4 F FOR 4 L20 REC. 1247 10M—15-11-41 CHECKED BY DATE)		RECORDED BY DATE)
) R 5.4 F FIR 4 L 20 REO. 1247 10M-15-11-41	CHECKED BY DATE