	31	/ / /	27 26 25	24 23 22	21 21	0 19 1	18 17	16 15	14 13	12 11	و (10	8 7	5	4 3	2 1		
7 7			i ki ki ci chi	en in a	STAB W	5. 12. 26. 21. 21. 21. 21. 21. 21. 21. 21. 21. 21	AR LUSE	RHILL OR W	MOUNT.	SEIMPET	000 (84) 848. 848	1 118 146 25 25	STR. CREMA	120 140 0 0 150 150 150 150 150 150 150 150 15	18		
- °/					AIRFRAME FAILURE					$\frac{Y}{1}$	ENGINE FAILURE)./ <u>=</u>		
• • /	A/C								ACCIDENTS					FAILURE POOR			
	AO.	UNIT 13 E.F.T.S. COM.			PLACE					DATE 15-12-42 TIME 0845				1 1 1/2	S' /		
V /4	Z Z	St. Euge	ene. Ont.	# 3	11) yard	s S.	of M.	Α		1.]	100-45-		_ ≤ ``,	(HE)		
(°)	٦	A/C TYPE	-4 mi1	T.T	No.	4000		CRASH CAT.	C 2	SE	ME	DAY	NIGHT	101017	THER TO		
		<u> </u>	et Finch Name		ANK	4557	DUTY	<u> </u>	LNJU	RIES		SE	RIOUS		Supt. 0		
(0 /		0-1-	enck, E.		4.0 0	00000) PF) ••				FATAL	INJURY		3//12		
		Sche	enck, 2.	•	AU R.	129999	7	N.	il					1.151/8	٠/ / - - ا		
^v	N N													∃ 121/3	^/ /=		
	ENGINE												IARD HAL NO.	S SH	, r ⁱ		
<u> </u>	OF E											_	1		, Kg/ "		
(Z	PE												Δ		__\		
- º	۲	TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT	SERIAL No.	DAT	E	н			Y PILOTS		111/	87 /		
			155			140.		INS	T. NIGHT	ON T		TOTAL SO	LAST 6 MOS		// / 。		
┈┢	_	Finch II	4557	Seriou	S										*/		
<u>`</u>	GORY	kinner d	2 42/158 8	 											~		
	EGO														(ATA)		
1 2	CATE	SIGNAL NO	. & DATE	UNIT No. & D	ATE	COM.	No. & E	ATE	REPO	RT	Fil	_E	DATE	I I K	ξ/ ² 2.\ n =		
	\mathcal{I}	E 206	16 -12		N A 7 :	10.5	O F	A C C .	DENT						17. 19. 19. N		
◊ ⊁	_	, , , , . ,	,,-,-,	1-1-1	NATI				DENT		0. / 0	/ / /	a /a /		\rightarrow		
	7	E V S	9 4 8	6 01 11	21 E	3/ 1	31 31	21 81	61 05	12 22	2/23/ Ez 72		2 82 82		SE SE		

ľ	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	,
)	Solo practice flight.	OR COMMANDING OFFICER'S REPORT:	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	
)))	Aircraft was taking off. Engine failed at 200 feet. Pupil carried out forced landing in field covered with snow causing aircraft to turn over.	D-14 DATE: COMPOSITION: OF M/E S/MC/PM/O RECOMMENDATIONS:)
))
))))	PRIMARY CAUSE: Inexperience on part of pilot, in failing to revv the engine up sufficiently while waiting to take off to counteract for the extreme cold. 15. Forceo Land		
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
,	Engine failure shortly after take-of cold weather conditions, A/C force landed in field covered with snow,	RECORDED BY DATE)
)	A/C turned quer, on ital hack.	6. ENGINE TROUBLE - ACCIDENT DATE	ز
}	~~~~~ ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~)