31	/ <u>*</u> :///	27 26 25	/ / / /	'//	/ /	/ /	16 15 14 13 LULY OR OUT	///		8 7 118 646.	RESCRIPTION	4 3 2	/
Į.	PILOT	OTHERS		AIRF	RAME	FAIL	URE		ENGIN		V V V V V V V V V V V V V V V V V V V		/
YPE OF A	C A C UNIT 1 0.T.U. COM. Bagotville EAC A/C Hurricane 11B				=	. St.	Honore, P	DATE			1600 33	Z NSTS	_
	Hurric	cane 11B	Ta	No.	5621 No.		CAT. A	JRIES		DAY X	ious		
	Lorime	er, D.R.	P	/0 19		P. P.	Killed NiL.		15 <u>1</u> ,	FATAL 1	INJURY	S P P	
OF ENGINE											ARD IAL No.	O UNDITO	
TYPE	TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DAT	E INST. NIGH	ON	LOWN BY	PILOTS TOTAL	LAST	T A CALL	/
1	Hurricane P. Merlin	n A265493	1/A539 To	ta1			INST. NIGH	DUAL	SOLO D	UAL SOL	O 6 MOS.	[] (S)	<i>′</i>
TEGOR	Hurrican P.Merlin signal no.	A265398,			COM.	No. & C	ATE REP	ORT	FILE		DATE		25'/
	A-79 1	-1 2 -4 2		NATI	JRE	O F	ACCIDEN	т					
2		6 6 4	6 01 11	21 E	71 9	91	71 81 61 02	15 55	1 ² /1 ³ /1	56 26 26	72 82	62 06 18	ant 2

)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER)							
)	Operational training-Search	OR COMMANDING OFFICER'S REPORT:								
)	formation practice.	COURT OF INQUIRY	,							
,	NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/C 5626 & 5433 ON AUTHORIZED FORMATION	DATE: 5-12-42	,							
,	PRACTICE WAS JOINED BY OTHER A/C AND CARRIED	COMPOSITION:								
)	out part of exercise and separated. A/C 5626 called 5433 by R/T to reform "VIC". 5433	J.F. Scholes, F/L. #1 O.T.U. Bagotville.								
)	APPROACHED BELOW AND ASTERN AND CUT OF TAIL)							
)	of 5626. Pilot of 5433 ATTEMPTED FORCED	RECOMMENDATIONS:								
١	LANDING AND CRASHED. PILOT OF 5626 BAILED OUT TO SAFETY.	That all pilots be impressed that chances of making								
	DDIMADY CAUCE	a successful forced landing under similar conditions)							
)	PRIMARY CAUSE: Collision in mid sir.	would be of a low percentage.)							
))							
)	21. COLLISIONS A/C.)							
,		ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	•							
/)	121	CONCLUSIONS OF A.L.B.	ĺ							
,	\ /	WHILE AGREEING WITH THE FINDINGS IT IS CONSIDERED THAT SOME BLAME	•							
,	\smile	SHOULD BE ATTACHED TO W.O.2 COX FOR ATTEMPTING TO JOIN THE FORMATION								
)		THUS CONTRAVENING C.A.P. 100, Sec. 1 PARA-25 AS HIS DOING SO MIGHT)							
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	HAVE CONTROBUTED IN SOME WAY TO THE SUBSEQUENT COLLISION BETWEEN THE								
)	Primarily, orror in judgment on	AIRCRAFT OF P.O. LORIMER AND P.O. CORRIGAN.	ì							
١	the part of P.O. Lorimer.	RECORDED BY DATE	_							
)							
)	R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE)							
)			١							