31	/	*//////////////////////////////////////	//,	20 19 18 20 19 18 218 175 685 578 178 16	17 16 2 17 16 2 15 Q ² H	15 14 OR WOLL	13 1 1,70 1,70	777	9 8	7 6 5	4 3 2 * Green 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
F A/C		PILOT OTHERS		FRAME ES O	FAILUE			ENG	INE F	AILURE	1 1 1
TYPEO	F	"" 121 Squadron	C. Ar	nold Co	CA'	ASH 8 T.	<u></u>	H.Q. FILE SE ME	110	0-4-60 Y NIGHT	3 WENTHER
		Gregory H.W.	Sgt. F/SGT	R4840	Pass.	Nil	1 J U I	RIES	F	SERIOUS ATAL INJUR	C F NO D REPORTED
OF ENGINE										SERIAL NO.	P PRIME
TYPE	-	TYPE A/F No. EXTENT OF DAMAG		SERIAL No.	DATE	INST. N		URS FLOWN	тот	TAL LAS	ST TO LANDING
A V NO		Lysander 460 Seri Perseus 28025/2053 Serio	ou sly us					DUAL SOLO	DUAL	SOLO 6 MC	
CATEGO	ı	SIGNAL NO. & DATE UNIT NO. &			No. & DAT	E	REPO	RT F	FILE	DATE	THE STREET
<u>,</u> ' [/ z	7 / 3 / 4 / 5 / 6 / 1 / 8 / 6 / 01 S F S 9 L B 6 01	15/3	URE EI FI	6 6	1/0/3	3/20		bs es	92 42 8	02 62 0E 1E

(-) (-) (-) (-) (-) (-) (-) (-) (-) (-)	
DUTY ON WHICH ENGAGED: Search for lost Hurricane. 5496. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Forced landing on road. Ran out of gas, and was lost. Another pilot, unskilled in navigation, was acting as observer.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: DATE: 22-12-42. COMPOSITION: P/O Friedlander, J.B. (#5 (C.A.C.) Detachment. FMARLE SALES AND ADDRESS OF THE SALES AND ADD
) PRIMARY CAUSE:) Description of part of live, mitigated alighter by a compart of live.	THAT THE OFFICER COMMANDING COMPOSITE SQUADRONS ENSURE THAT THE NAV- IGATIONAL ABILITY OF HIS PILOTS ON TEMPORARY DUTY BE CHECKED IN A PRACTICAL WAY AND STEPS BE TAKEN TO INSTRUCT THOSE FOUND TO BE DEFICIENT. THAT, IF PRACTICAL, THE RADIO EQUIPMENT BE MODIFIED SO THAT THIS RADIO BEAM COULD BE USED. THAT A QUALIFIED RADIO OPERATOR OR NAVIGATOR FORM PART OF THE CREW WHEN IT IS NECESSARY TO FLY IN DOUBTFUL WEATHER.
) FORCED LANDING (17)	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NiL. CONCLUSIONS OF A.I.B. A/C force landed when fuel supply became low. Pilot on "search" flight became lost due to poor airmanship.
SECONDARY CAUSE OR CONTRIBUTING FACTORS: A/U force landed, A/U struck stone throwing A/C over on back, BETROL. SHORTAGE R.C.A.F. FORM LZO REO. 1247 1CM—15-11-41	RECORDED BY DATE CHECKED BY DATE