υ	PILOT OTHERS	All	RFRAME	FAILUR	E		STO STO STORE STOR	Street India of the
E OF A	UNIT 32 0.T.U; COM.		ACE		IDENTS	DATE2C-12-	-42 TIME 1242	1 1 / .6
门	Patricia Bay, B.C. W.A. A/C TYPE Harmdon T	N C		18 BAY CRA CAT		SE ME	DAY NIGHT	o wer
	Hampden I	RANK	No.	צדטפ	1010	RIES	SERIOUS FATAL INJURY	≓cl' I / .9
E OF ENGINE	Doyle, J. RAF Richards, A.S Slater, C.A. Herreiven D. RAF Graham, J.A.	SGT	1344369 R118264 R51689 1068199 R106528	WOAG WOAG ACP	Nil Nil Nil Nil		CARD SERIAL NO.	S N Z EU S O S S E M S S S S S S S S S S S S S S S S
TYP	TYPE A/F NO EXTENT	REP	ORT SERIAL	DATE	но	URS FLOWN B	Y PILOTS	1 / 0
	a engine No. of Dama. Hanpden I ANIOI Serious	GE FO	RM No.	DATE	INST. NIGHT	ON TYPE	TOTAL LAST DUAL SOLO 6 MOS	
, KY	Pegasus A126015/A1519PS		nt					A G R OF S

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Local flying.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Aircraft approaching to land when at 30 feet swung to port then collided with aerodrome control pilots trailer at side of runway.	D-14 COMPOSITION: CO/255/wvco/wwc RECOMMENDATIONS:
PRIMARY CAUSE: Pilot's error.))
, -)
6. COLLISIONS	
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
,	Disciplinary action against the Flight Commander
	concerned is being taken by Commanding Officer.
CECONDADY CAUGE OF CONTROLLING	· .
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	1
A/C swung and collided with acrodrom	DECORDED BY DATE
control pilots trailer. Rapid closing in of weather and 150 crosswind.	<u>ng</u>
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE)