A/C	DISON ALCO PIL		OTHERS	\$ 148 (1) \$ (1) \$ (2) \$		FRAME	FAIL	URE	,	<u> </u>	ENG		STR. CREWA	Surfe Just
ПО			F.T.S. arines	сом. 1	PLA	CE	F A	CCIDE	NTS		6-1-	·43 TIME	1605	
ΤΥF	A/C TYPE		r Loth		No.	<u> </u>		CRASH CAT.	<u>.</u>	SE X	ME	DAY	NIGHT	3 - S NE
_			name aford, B.	+	RANK	No. R <b>160401</b>	DUTY PP	Nil	U L N I	RIES		SEI FATAL	RIQUS INJURY	755/5
TYPE OF ENGINE		E A/F		EXTENT	REPO	RT SERIAL			НО	URS FL	- NWC		ARD HAL NO.	
	& EN	GINE	No.	OF DAMAG	E FOR		DATE	·	NIGHT	ON T		TOTAL	LAST 6 MOS	; [ ] -1 / <sub>4</sub>
GORY	] Gyn	er mo sy 15a	oth 8358 1jor 2453	/89296 "	Can									
TEG		IAL NO	& DATE	UNIT No. &	DATE	сом.	No.& D	ATE	REPO	RT	FI	LE !	DATE	

			<b>)</b> ) ) ) )	) ) ) )
) )	Duty on which engaged: Solo flying practice on sequences 7-8-10-12-5-17.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	D-14	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT: Flane bounced and came down facing	DATE: COMPOSITION: LH/PSHL/XG	-M.	,
)	edge of runway. Hitting the snow,	COMPOSITION.		,
)	caused plane to tip onto its nose, breaking propellor.	/		
)		RECOMMENDATIONS:		)
)				
)	PRIMARY CAUSE:  40. Heavy landing flying into ground.			
)	4. Heavy	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER More dual on correcting for dribeing given to pupil before fur		) ng is ,
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:			,
)	Heavy snow bank on edge of runways.	RECOR	RDED BY	DATE
)				,
,	R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41	CHECK	KED BY	DATE )
1			) ) ) ) )	) ) ) )