

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Parking a/c following solo practice. OR COMMANDING OFFICER'S REPORT:

MULI ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

TC A/PCT/XGG
MA/XA
D-14

Pilot of 4374 taxiing into line with COMPOSITION:

mechanic on wing tip attempted to swing aircraft into small space and collided with aircraft 1219 which was stationary on line.

RECOMMENDATIONS:

More ground crew on field with strict orders to give material assistance to pilots taxiing A/C.

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

9. Collision

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

48 hours detention.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~mechanic gave insufficient assistance on wing tip, 4374 collided with 1219 parked on line.~~

RECORDED BY

DATE

CHECKED BY

DATE