

) DUTY ON WHICH ENGAGED:) Taking off into wind.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
) NATURE OF ACCIDENT AND STAGE OF FLIGHT:) A/c undershot rolled section of field and landed in deep snow causing a/c to overturn .	DATE: COMPOSITION: LU/PS-/XGM)
)	RECOMMENDATIONS: .)
))
) PRIMARY CAUSE:	`)
30. Undershooting runway.	
; 3. Underskat	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
)	Recommended to the Department of Transport that
	better Boundary markers be obtained.
	Boundary markers in the form of red flags to be
	placed around west field.
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Neglect and ourelessness on part of	Pupil placed on charge. Dismissed. Advised to use more caution in future.
student.	RECORDED BY DATE
Itght condition rendering boundaries	
Obscure - R.C.A.F. FORM L20 REQ. 1217 10M-15-11-41	CHECKED BY DATE