	PILOT OTHERS					AIRFRAME FAILURE											
POUNIT	UNIT 2 E.F.T.S. COM.				PL E DATE 25-2-43 TIME 100								000				
H A/C	Fort William 2				_5	mi. N	of aer		rodrome.			FILE 1	700-4	323	M I S		
	TYPE T/Noth				No.	4323		CRAS CAT.	ян 1	l	SE X	ME			NIGHT		
_	NAME					No.	DUTY	INJUR				<u> </u>		SERIO	S C E L L A I		
PE OF ENGINE	Graham, R.N.				; R.	175140	Pp		Cille	2d.				CAF SERIA		S S S S S S S S S S S S S S S S S S S	
	TYPE A/F No. EXTENT			RE	EPORT	SERIAL	DAT	F		НС	URSF	LOWN	BY PILO	OTS	111/		
	oth 4		of damag otsl	E F	ORM	RM No.			INST. NIGHT		ON TYP			DTAL SOLO	LAST 6 MOS	STA A	
Ma	or 7323	1/2/T-45	Cotel													O M	
ш	NAL No. & I		UNIT No. &				No. & I			REPO		T	ILE	<u> </u>	ATE	H T S	

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER Solo circuits and steep turns. OR COMMANDING OFFICER'S REPORT: NATURE OF ACCIDENT AND STAGE OF FLIGHT: L. E.W.C.Sharpe (C2797) A/c fell into spin or spiral dive COMPOSITION: while practising steep turns and complete recovery was not effected before hitting ground. RECOMMENDATIONS: In view of fact that cause of accident obscure, it seems impossible to make any recommendations that can definitely be applied to this accident. but it is PRIMARY CAUSE: possible that accident might have been avoided had the 18. Loss of control. instructor given more serious consideration of this Obscure, but probably due pupil's somewhat erratic progress in flying. merienced vilot's inabidity ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER recover from a dive after recovery at low altitude from a spin or a CONCLUSIONS OF A.I.B. Cause of accident due to an inexperienced pilot failing to make recovery from a spin or spiral dive. (See Summary of Accident Investigation #800) RECORDED BY DATE CHECKED BY DATE R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41