

DUTY ON WHICH ENGAGED: Flying training.	OR COMMANDING OFFICER'S REPORT: D-14
Taxiing A/C from the front seat to the rank. Pilot took a wide sweep around and taxied over a	D-14 DATE: COMPOSITION: TCO/PCT/X6M
bad patch marked with a red flag. The flag struck the centre sect on and made a hole in the plywood.	RECOMMENDATIONS:
PRIMARY CAUSE: 2. Hitting obstructions.	
9. Callisians	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Sgt. Ansley's log book endorsed for carelessness.
secondary cause or contributing factors:	
	RECORDED BY DATE