

BUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Mutual Instruction.	OR COMMANDING OFFICER'S REPORT:
	D-14.
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
Port wheel struck a large piece of	COMPOSITION: 7 6 5 / 2 5 **
ice whilst taxying along No. 1 run-	
way. A/C swung to port and port	
wing struck snow bank at side of	
runway.	RECOMMENDATIONS:
•	
PRIMARY CAUSE:	
2. Hitting obstructions.	
	ACTION TAKEN:
	(A) Disciplinary (9) Technical (C) Other
	(A) Sgt. Truswell's Log Book endorsed for
	error in judgment.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
SECONDARY CAUSE OR CONTRIBUTING FACTORS: 32. Pilot error.	
	RECORDED BY DATE
	RECORDED BY DATE
	RECORDED BY DATE CHECKED BY DATE