



DUTY ON WHICH ENGAGED:

Training Cross Country flight.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Failure of stbd engine caused A/C to force land in soft snow.

DATE:

COMPOSITION:

EB/POD/ES/CO/D/I ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

54. Engine failure in the air.

Loose snow sucked into the air intake, probably while a/c was waiting to take off, caused stbd engine to fail.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

7. Forced Landing 17

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

37. Overturning.

26. Engine trouble - accident

RECORDED BY

DATE

CHECKED BY

DATE