

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Dual night landings.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: COMPOSITION: LO PSO/I BBG X6/-/X6/
/C ran off aemodrome due to icy urface, A/C tipped over on its	COMPOSITION: 10 / 130/I / 08 6 X 6/7/X6/
ose in deep snow.	
	RECOMMENDATIONS:
PRIMARY CAUSE: 2. Pilot error.	
A/c landed too fast in no wind	
conditions. An inexperienced	ACTION TAKEN
instructor who should have taken corrective action earlier.	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other
	The instructor has been reproved.
secondary cause or contributing factors:  4. Bad surface.	
6. Nosing up.	RECORDED BY DATE
Icy surface of aerodrome.	
	CHECKED BY DATE