

DUTY ON WHICH ENGAGED: Progress check.	COURT OF INQUIRY, INVESTIGATING OFFICE OR COMMANDING OFFICER'S REPORT:	<u>ER</u>	
nature of accident and stage of flight: Pupil made normal landing and rolled 100'. A/C then turned to the right	DATE: COMPOSITION:	D-14)
and instructor took over but could not keep A/C from turning due to the U/C gradually collapsing.	RECOMMENDATIONS: Suggest immediate action on	modifications.)
) PRIMARY CAUSE: 33. Technical defect. U/C tube bracket bots sheared.)
)))	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) O	THER)
))
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
)		RECORDED BY	DATE
) R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41		CHECKED BY	DATE
(· · · · · · · · · · · · · · · · · · ·))))))))))