

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Wireloss exercise.	OR COMMANDING OFFICER'S REPORT: D-14 #6
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine failure, A/C made precautions landing.	OR COMMANDING OFFICER'S REPORT: DATE: P-14 #6 DATE: PSOMPOSITION:
	RECOMMENDATIONS: More careful inspection before engine declared serviceable.
PRIMARY CAUSE: 54. Engine failure in the air. Three of No. 7 Cyl.hold-down studs were broken and nuts off remaining studs. Cyl.had lifted off crankcase and oil rings had caught under lip, breaking the piston. Particles of piston fell into crankcase.	Examination of loose nuts indicates that new ones were not used on overhaul by Standard Machine Wks., Wpg., contrary to C.A.P. 78, Vol. 2 leaf let M2/5/7.
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Nil.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
	RECORDED BY DATE
	CHECKED BY DATE