U	ŀ	COO NOT AND CONTROL OF THE STATE OF THE STAT				PAIN CONTRACTOR		Meser INDE	PRINTED FOR	ENGI		LURE	Nigot X	PRINTED A
PE OF A/	r	UNIT #32 O.T.U. COM. Patricia Bay #WAC	I.	PLACE		F A	CCID	ENTS	DATE H.Q. I		43 TIME] 3	115 15 14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
ΤY		A/C TYPE Hampden I		No.	AN.l	14	CRASH CAT.	В	SE	МЕХ	DAY	NIGHT	1 5 0	MEATHER DREAMS
_	Į	NAME	RANI		No.	DUTY		ועאו	RIES		SEI	เดบร] > [[DRY SURE
	L	Marsden, W.	PO	13	318924	P	o N	il			FATAL	INJURY	ا کا کا	DRATT A
YPE OF ENGINE												ARD IAL No.		OHICA OHICA PHICA
F		TYPE A/F No. EXTENT	RI GE F	PORT	SERIAL No.	DAT	Ξ	H	1		Y PILOTS		-	LENOHE LENDING
	F		ious		+		INS	T. NIGHT	DUAL :		TOTAL DUAL SOI	LAST _O 6 MOS	. -	/sti//
GORY	1	Pegasus P155526/5154856	5]	igh	tly		2	8 18	4	10	113 1	06	AGE O	(5) 4 /
TEG	-	SIGNAL NO. & DATE UNIT NO. 8	DAT	=	COM,	No. & D	ATE	REPO	RT	FIL	.E	DATE		1 \$7.5.7
Ö	H	A.354 7.543											11	12 12 340

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICE	
	OR COMMANDING OFFICER'S REPORT:	D.14 #1
Precautionary landings	1	1
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	Surloant 10BI
Strong wind blowing down runway.	COMPOSITION: / //////////////////////////////////	Helpen Jobs
Made normal approach, but bounced		i de la companya de
badly. Apparently braked too	· ·	
harshly with control column forwar	d. RECOMMENDATIONS:	
Tail came up & nose struck ground.		
Both propellors & nosed badly dama	ged.	
PRIMARY CAUSE:		
36. Nosed up		
HEAVY 4	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHE	ER
	Log Book endorsed "Careles	sness"
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
40. Heavy landing - flying into	around	
		RECORDED BY DATE
4. Harsh use of brakes		5,000
		CHECKED BY DATE